

Tender Fee: Rs. 2,000/-  
(Non-Refundable)

## TENDER FORM

### Tender # RM/01/22-23 Repair & Maintenance of Hino Bus & Hino Coasters

Date of Issue : June 8, 2023  
Last Date of Submission : June 23, 2023 (3:00 PM)  
Date of Opening of Tender : June 23, 2023 (3:30 PM)

Company Name: HINO HAWKSBAV

NTN: 4417675-9, SRB Registration Number: 4417675-9

GST Registration Number: \_\_\_\_\_

Pay Order / Demand Draft # 9949.4772989, Dated: 23-6-2023

Amount of Rs. 282500, Drawn on Bank: Nicezan Bank



**7. Bill of Quantity:**


Sr #	Description	Qty	Amount
1.	<b>Repair &amp; Maintenance of Hino Bus</b> <b>Model: AK1J, Vehicle Reg # GA-7901</b> <u>Scope of Service:</u> Complete renovation of bus body includes the following items a) MS Sheet A Zone Change (As per approved sample) new sheets of 18 SWG size: 4' x 8' b) MS Sheet B Zone Change, new sheets of 18 SWG size: 4' x 8' c) Complete roof outer sheet change, new sheets of 18 SWG size: 4' x 8' d) Complete Roof and inner sides) and placed new sheets with a thickness of 2 mm. (As per the approved sample) sheet change and Floor matt and wood change complete e) Complete chassis anti-rust paint f) Front wind screen removing hinges repair & refitting g) Rain silver Patti removing & new installation h) All window removing hinges repair & refitting i) Repairing of Front & Rear Panels j) Repairing of Front & Rear Bumpers k) Roof Ventilator replace l) Replacement of roof lights, Roof indicator change (Outside) and Complete Electrical system checking, repairing & replacement of defective appliances m) Trunk Repair n) Passenger & Driver door repair o) Front both side window sliding repairing p) Front & rear both side pillars repairing q) Affected Bus Body repainting with oil paint as per colour scheme r) All seat repair cushion work, Damage seat repair & Complete Engine Bonnet repairing & re-carpeting, Cushioning work and change of rexine (As per approved sample) s) Mudguard changes both sides t) All window frame & Pillar repair	1 Job	220000

  
**SHAH AB UDDIN KHAN**  
 Member PC-B  
 Manager Admin, IBA Karachi


  
**MUHAMMAD NAVEED AKHTAR**  
 External Member PC-B  
 Chief Accounts Officer,  
 KIBGE, University Of Karachi


  
**MIRZA MUDASSIR BAIG**  
 Member PC-B  
 Sr Exec Finance, IBA Karachi

  
**MUHAMMAD HANIF**  
 Member PC-B  
 Sr. Exec Purchase, IBA Karachi

  
**OSAMA A. QAYOOM**  
 External Member PC-B  
 Head of Biomedical Engineering  
 Department, Dow University

  
**MANSOOR ALI**  
 Member PC-B  
 Manager IT, IBA Karachi

  
**MUHAMMAD ANWAR**  
 Chairperson PC-B  
 Chief Librarian, Karachi

  
 Stamp & Signature



Sr #	Description	Qty	Amount
2.	<b>Repair &amp; Maintenance of Hino Coaster</b> <b>Model: GB2W, Vehicle Reg # GA-6869</b> <u>Scope of Service:</u> Complete renovation of bus body includes the following items a) MS Sheet A Zone Change (As per approved sample) new sheets of 18 SWG size: 4' x 8' b) MS Sheet B Zone Change, new sheets of 18 SWG size: 4' x 8' c) Complete roof outer sheet change, new sheets of 18 SWG size: 4' x 8' d) Complete roof inner wooden sheet change, Complete both side wood sheet new installation inner and Floor matt and wood change complete e) Complete chassis anti-rust paint f) Front wind screen removing hinges repair & refitting g) Rain silver Patti removing & new installation h) All window removing hinges repair & refitting i) Repairing of Front & Rear Panels j) Repairing of Front & Rear Bumpers k) Roof Ventilator replace l) Replacement of roof lights, Roof indicator change (Outside) and Complete Electrical system checking, repairing & replacement of defective appliances m) Trunk Repair n) Passenger & Driver door repair o) Front both side window sliding repairing p) Front & rear both side pillars repairing q) Affected Bus Body repainting with oil paint as per colour scheme r) All seat repair cushion work, Damage seat repair & Complete Engine Bonnet repairing & re-carpeting, Cushioning work and change of rexine (As per approved sample) s) Mudguard changes both sides t) All window frame & Pillar repair	1 Job	1,700,000

  
**SHAH AB UDDIN KHAN**  
 Member PC-B  
 Manager Admin, IBA Karachi

  
**MUHAMMAD NAVEED AKHTAR**  
 External Member PC-B  
 Chief Accounts Officer,  
 KIBGE, University Of Karachi

  
**MIRZA MUDASSIR BAIG**  
 Member PC-B  
 Sr Exec Finance, IBA Karachi

  
**MUHAMMAD HANIF**  
 Member PC-B  
 Sr. Exec Purchase, IBA Karachi

  
**OSAMA A. QAYOOM**  
 External Member PC-B  
 Head of Biomedical Engineering  
 Department, Dow University

  
**MANSOOR ALI**  
 Member PC-B  
 Manager IT, IBA Karachi

  
**MUHAMMAD ANWAR**  
 Chairperson PC-B  
 Chief Librarian, Karachi





Sr #	Description	Qty	Amount
3.	<b>Repair &amp; Maintenance of Hino Coaster</b> <b>Model: GB2W, Vehicle Reg # GA-6867</b> <u>Scope of Service:</u> Complete renovation of bus body includes the following items a) MS Sheet A Zone Change (As per approved sample) new sheets of 18 SWG size: 4' x 8' b) MS Sheet B Zone Change, new sheets of 18 SWG size: 4' x 8' c) Complete roof outer sheet change, new sheets of 18 SWG size: 4' x 8' d) Complete roof inner wooden sheet change, Complete both side wood sheet new installation inner and Floor matt and wood change complete Removing/scrapping of existing formica sheets (Full inner side) and placing new sheets with a thickness of 2mm. (As per approved sample) e) Complete chassis anti-rust paint f) Front wind screen removing hinges repair & refitting g) Rain silver Patti removing & new installation h) All window removing hinges repair & refitting i) Repairing of Front & Rear Panels j) Repairing of Front & Rear Bumpers k) Roof Ventilator replace l) Replacement of roof lights, Roof indicator change (Outside) and Complete Electrical system checking, repairing & replacement of defective appliances m) Trunk Repair n) Passenger & Driver door repair o) Front both side window sliding repairing p) Front & rear both side pillars repairing q) Affected Bus Body repainting with oil paint as per colour scheme r) All seat repair cushion work, Damage seat repair & Complete Engine Bonnet repairing & re-carpeting, Cushioning work and change of rexine (As per approved sample) s) Mudguard changes both sides t) All window frame & Pillar repair	1 Job	1650000

SHAH AB UDDIN KHAN  
Member PC-B  
Manager Admin, IBA Karachi

MUHAMMAD NAVEED AKHTAR  
External Member PC-B  
Chief Accounts Officer,  
KIBGE, University Of Karachi

MIRZA MUDASSIR BAIG  
Member PC-B  
Sr Exec Finance, IBA Karachi

MUHAMMAD HANIF  
Member PC-B  
Sr. Exec Purchase, IBA Karachi

OSAMA A. QAYOOM  
External Member PC-B  
Head of Biomedical Engineering  
Department, Dow University

MANSOOR ALI  
Member PC-B  
Manager IT, IBA Karachi

MUHAMMAD ANWAR  
Chairperson PC-B  
Chief Librarian, Karachi

Stamp & Signature  
HINO HAWKS BAY  
AUTHORISED HINOPAK DEALER  
Page 15 | 23



Sr #	Description	Qty	Amount
4.	<b>Repair &amp; Maintenance of Hino Bus</b> <b>Model: AK1J, Vehicle Reg # GS-9439</b> <u>Scope of Service:</u> Complete renovation of bus body includes the following items a) MS Sheet A Zone Change (As per approved sample) new sheets of 18 SWG size: 4' x 8' b) MS Sheet B Zone Change, new sheets of 18 SWG size: 4' x 8' c) Complete roof outer sheet change, new sheets of 18 SWG size: 4' x 8' d) Complete Roof and inner sides) and placed new sheets with a thickness of 2mm. (As per approved sample) sheet change and Floor matt and wood change complete e) New installation of the front passenger Passenger door f) Complete chassis anti-rust paint g) Front wind screen removing hinges repair & refitting h) Both aside mirror new installation i) Rain silver Patti removing & new installation j) All window removing hinges repair & refitting k) Repairing of Front & Rear Panels l) Repairing of Front & Rear Bumpers m) Roof Ventilator replace n) Replacement of roof lights, Roof indicator change (Outside) and Complete Electrical system checking, repairing & replacement of defective appliances o) Trunk Repair p) Passenger & Driver door repair q) Front both side window sliding repairing r) Front & rear both side pillars repairing s) Affected Bus Body repainting with oil paint as per colour scheme t) Complete Engine Bonnet repairing & re-carpeting (As per approved sample)	1 Job	2200000

**SHAH AB UDDIN KHAN**  
Member PC-B  
Manager Admin, IBA Karachi

**MUHAMMAD NAVEED AKHTAR**  
External Member PC-B  
Chief Accounts Officer,  
KIBGE, University Of Karachi

**MUHAMMAD HANIF**  
Member PC-B  
Sr. Exec Purchase, IBA Karachi

**MIRZA MUDASSIR BAIG**  
Member PC-B  
Sr Exec Finance, IBA Karachi

**OSAMA A. QAYOOM**  
External Member PC-B  
Head of Biomedical Engineering  
Department, Dow University

**MANSOOR ALI**  
Member PC-B  
Manager IT, IBA Karachi


**MUHAMMAD ANWAR**  
Chairperson PC-B  
Chief Librarian, Karachi







Sr #	Description	Qty	Amount
5.	<b>Repair &amp; Maintenance of Hino Coaster</b> <b>Model: FB2W, Vehicle Reg # GS-9520</b> <u>Scope of Service:</u> Complete renovation of bus body includes the following items a) MS Sheet A Zone Change (As per approved sample) new sheets of 18 SWG size: 4' x 8' b) MS Sheet B Zone Change, new sheets of 18 SWG size: 4' x 8' c) Complete roof outer sheet change, new sheets of 18 SWG size: 4' x 8' d) Complete roof inner sheet change, Complete both side wood sheet new installation inner and Floor matt and wood change complete e) Complete chassis anti-rust paint f) Front wind screen removing hinges repair & refitting g) Rain silver Patti removing & new installation h) All window removing hinges repair & refitting i) Repairing of Front & Rear Panels j) Repairing of Front & Rear Bumpers k) Roof Ventilator replace l) Replacement of roof lights, Roof indicator change (Outside) and Complete Electrical system checking, repairing & replacement of defective appliances m) Trunk Repair n) Passenger & Driver door repair o) Front both side window sliding repairing p) Front & rear both side pillars repairing q) Affected Body repainting with oil paint as per colour scheme r) All seat repair cushion work and Complete Engine Bonnet repairing & re-carpeting	1 Job	165,000

  
**SHAH AB UDDIN KHAN**  
 Member PC-B  
 Manager Admin, IBA Karachi

  
**MUHAMMAD NAVEED AKHTAR**  
 External Member PC-B  
 Chief Accounts Officer,  
 KIBGE, University Of Karachi

  
**MUHAMMAD HANIF**  
 Member PC-B  
 Sr. Exec Purchase, IBA Karachi

  
**MIRZA MUDASSIR BAIG**  
 Member PC-B  
 Sr Exec Finance, IBA Karachi

  
**OSAMA A. QAYOOM**  
 External Member PC-B  
 Head of Biomedical Engineering  
 Department, Dow University

  
**MANSOOR ALI**  
 Member PC-B  
 Manager IT, IBA Karachi

  
**MUHAMMAD ANWAR**  
 Chairperson PC-B  
 Chief Librarian, Karachi





Sr #	Description	Qty	Amount
6.	<b>Repair &amp; Maintenance of Hino Bus</b> <b>Model: FB2W, Vehicle Reg # EB-2245</b> Complete renovation of bus body includes the following items a) Complete new roof upper and lower side replacement (As per approved sample) new sheets of 18 SWG size: 4' x 8' b) Complete both side wood sheet new installation inner, Floor Wood & matt change and Complete Engine Bonnet repairing & re-carpeting c) Repairing of Front & Rear Panels d) Repairing of Front & Rear Bumpers e) Roof Ventilator replace f) Replacement of roof lights, Roof indicator change (Outside) and Complete Electrical system checking, repairing & replacement of defective appliances g) Trunk Repair and proper fixing h) Passenger & Driver door repair i) Front wind screen removing hinges repair & refitting j) Front & Rear both side wheel housing or mudguard repairing k) Affected Bus Body repainting with oil paint as per colour scheme	1 Job	750000
7.	<b>Repair &amp; Maintenance of Hino Coaster</b> <b>Model: GB2W, Vehicle Reg # GS-985-B</b> Complete renovation of bus body includes the following items a) Complete both sides 2 mm wooden sheet new installation inner b) All seat cushion and foam repairing work, Complete Engine Bonnet repairing & re-carpeting c) Repairing of Front & Rear Panels d) Repairing of Front & Rear Bumpers e) Roof Ventilator replace f) Replacement of roof lights g) Roof indicator change (Outside) h) Trunk Repair i) Passenger & Driver door repair j) Front both side window sliding repairing k) Rear both side Pillar repairing l) Complete Electrical system checking, repairing & replacement of defective appliances m) Affected Bus Body repainting with oil paint as per colour scheme and Denting/Painting work (minor fabrication if any)	1 Job	600000

SHAH AB UDDIN KHAN  
Member PC-B  
Manager Admin, IBA Karachi

MUHAMMAD NAVEED AKHTAR  
External Member PC-B  
Chief Accounts Officer,  
KIBGE, University Of Karachi

MUHAMMAD HANIF  
Member PC-B  
Sr. Exec Purchase, IBA Karachi

MIRZA MUJASSIR BAIG  
Member PC-B  
Sr Exec Finance, IBA Karachi

OSAMA A. QAYOOM  
External Member PC-B  
Head of Biomedical Engineering  
Department, Dow University

MANSOOR ALI  
Member PC-B  
Manager IT, IBA Karachi

MUHAMMAD ANWAR  
Chairperson PC-B  
Chief Librarian, Karachi


Stamp & Signature  
HAWKSBAY  
AUTHORISED HINOPAK DEALER  
18/1/23



Sr #	Description	Qty	Amount
8.	<b>Repair &amp; Maintenance of Hino Coaster</b> <b>Model: GB2W, Vehicle Reg # JB-0036</b> <u>Scope of Service:</u> Complete renovation of bus body includes the following items a) MS Sheet A Zone Change b) MS Sheet B Zone Change c) Complete roof outer sheet change d) Complete roof inner sheet change, Complete both side wood sheet new installation inner and Floor matt and wood change complete e) Complete chassis anti-rust paint f) Front wind screen removing hinges repair & refitting g) Rain silver Patti removing & new installation h) All window removing hinges repair & refitting i) Repairing of Front & Rear Panels j) Repairing of Front & Rear Bumpers k) Roof Ventilator replace l) Replacement of roof lights, Roof indicator change (Outside) and Complete Electrical system checking, repairing & replacement of defective appliances m) Trunk Repair n) Passenger & Driver door repair o) Front both side window sliding repairing p) Front & rear both side pillars repairing q) Affected Bus Body repainting with oil paint as per colour scheme r) All seat repair cushion work and Complete Engine Bonnet repairing & re-carpeting s) Mudguard change both side		17,00,000

	Total	12,500,000
	13% SST (if applicable)	1,625,000
	Grand Total	14,125,000

Total Amount Rupees (in words) Fourteen million one hundred twenty five thousand only.

  
**SHAH AB UDDIN KHAN**  
 Member PC-B  
 Manager Admin, IBA Karachi

  
**MUHAMMAD NAVEED AKHTAR**  
 External Member PC-B  
 Chief Accounts Officer,  
 KIBGE, University Of Karachi

  
**MUHAMMAD HANIF**  
 Member PC-B  
 Sr. Exec Purchase, IBA Karachi

  
**MIRZA MUDASSIR BAIG**  
 Member PC-B  
 Sr Exec Finance, IBA Karachi

  
**OSAMA A. QAYOOM**  
 External Member PC-B  
 Head of Biomedical Engineering  
 Department, Dow University

  
**MANSOOR ALI**  
 Member PC-B  
 Manager IT, IBA Karachi

  
**MUHAMMAD ANWAR**  
 Chairperson PC-B  
 Chief Librarian, Karachi



Stamp & Signature